PROPOSED LIDL STORE BELMONT ROAD HEREFORD

ARBORICULTURAL METHOD STATEMENT

Rev 9 March 2022 Rev 20 August 2022 14 September 2022 Rev 22October 2022

ARBORICULTURALIST
David Rice Forestry
Cefnllwydcoed
Salem Road. Llandeilo
Carmarthenshire SA19 7LR
Tel 01558 824019
davidrice2@talktalk.net

1.0 ARBORICULTURAL METHOD STATEMENT

1.1 INTRODUCTION

The extent of the tree survey is within the site boundary area of the Three Counties Hotel on Belmont Road Hereford and trees off site to the west by Newton Brook and in the east in the adjacent housing area and the woodland in the south east corner.

The Tree Survey was commissioned by Lidl and undertaken on 16 December 2021 by David Rice Forestry. David is a qualified arboriculturalist of many years of experience and expertise in forestry.

1.2 **DOCUMENTS**

Drawing No CA HFD 2022-01 Rev E Lidl Hereford Tree Survey and Existing Features

Drawing No CA HFD 2022-02 Rev E Lidl Hereford Overlay &Tree Protection Plan

Drawing No CA HFD 2022-03 Rev B Lidl Hereford Landscape Proposals

Drawing No CA HFD-2022-04 Rev A Lidl Hereford Landscape Sections

Drawing No CA HFD-2022-05 Rev A Lidl Hereford Willow and Cherry Close Up

Tree Survey Hereford 16-12-2021 rev 20 August 2022

CA 2022 Lidl Hereford Planting Schedule 22 October 2022

1.3 TPO TREES

There is a TPO on the site for 4 Trees.

Hereford (2022) (No 666) Tree Preservation Order 17 August 2022
T1 Acer platanoides Norway Maple
T2 Cedrus deodar
T3 Prunus avium
Wild Cherry
T4 Salix babylonica
Weeping Willow
Grid Ref 349, 238,587
Grid Ref 349, 238,587
Grid Ref 349, 238,587

1.4. TREE SURVEY CATEGORIES

The tree categories used for the tree survey are

Condition A = Prime Condition

B = Sound Condition

C = Suspect Condition

U = Dead, dying, diseased. Remove/Fell

Amenity Value AV 1 = Very high value. Retention most desirable

2 = High Value. Retention desirable3 = Low Value. Could be retained

U = No value. Remove/Fell

1.5 **EXISTING SITE**

The Site comprises a large existing hotel building and a series of rooms around an internal courtyard with parking. There is an access road entrance from Belmont Road to and a large parking area adjacent to the west of the main hotel building.

The Site is centred at Ordnance Survey (OS) grid reference SO 49709 38572, in Hereford in Hereford County area and postal code HR2 7BP. The Site is roughly square shaped and covers an area of 1.68 hectares (ha).

The north boundary is a close boarded fence to residential rear gardens and is collapsed in one section. There is a grass between the fence and line of room. At each end of the north boundary are compost heaps screened by laurel hedges.

The eastern boundary of the Site is a line of mature shrubs trimmed to approximately 1.80m height a mix of deciduous and evergreen species behind a boundary closeboarded timber fence. Off-site

there is a narrow verge to a residential cul de sac. In the north corner by the compost heap and trimmed laurel hedge off-site are T12 and T13 Birch whose roots and canopies extend into the site. At the end of the cul de sac is a large T14 Sycamore off-site whose roots and canopy extend into the Site. There is then a 4m high conifer hedge inside the Site ending in an off-site G3 group of Ash.

A block of woodland cuts into the site in the south east section. There is a G4 an off-site group of Willow and Lime with roots and canopy extending into the Site. G5 Leyland Cypress are on site in front of a chainlink fence. This line of conifers are to be removed and to be replaced with a beech hedge.

The southern boundary starts at east by the woodland block and ends at Newton Brook in the west along Belmont Road. It is a busy road with a pedestrian cross over on the hotel frontage. The boundary is a low brick wall with a brick side walls at the entrance road to the hotel. There are planting beds at the entrance and along the entrance road up to the overhead sign. There is a walled pond and terrace on the hotel elevation with Belmont Road with a grass mound from the pond to the boundary wall. TPO3 T16 Wild Cherry, TPO4 T17 Weeping Willow are retained T15 Norway Maple and T19 Ash are trees around the pond are to be removed to facilitate adjusted ground levels required to develop the Site and T18 Lime removed due to poor health..

The remainder of the south boundary between the entrance road and the beech hedge by Newton Brook is TPO2 T1 Lebanon Cedar

The land on the other side of the Belmont Road is a large open space by a residential area with a hedge on the boundary with the roadside footpath

The land adjacent to the west boundary is a public open space with a footpath alongside Newton Brook separating the Site from a residential area. There are mature trees within the open space The first section of the Site western boundary is a mature trimmed beech hedgerow about 2m high continuing until the carpark area. The TPO 2 T1 Lebanon Cedar is in the grass area adjacent to the hedge. From the end of the hedge is a mature G1 Leyland Cypress group and after this group is a fenced boundary with a grass verge with isolated trees TPO1 T2 Norway Maple and in the north west end T3 and T4 Birch. This section has mature trees off-site by Newton Brook which overhang the Site.

Internally there are shrub beds around the main building in facing the west carpark and in groups in between the rooms around the internal courtyard. There is a line of T5 – T9 Lime in the carpark and two small Crab Apples between the courtyard rooms all are to be removed to facilitate the design.

2.0 TREE REMOVALS AND TREE WORKS

TREE REMOVALS

The following trees are recommended removals

• T18 Lime UU

The following trees are to be removed to facilitate the design and these occur within the site boundary.

- T5 Lime B2
- T6 Lime B2
- T7 Lime B2
- T8 Lime B2
- T9 Lime B2
- T10 Crab Apple B2
- T11 Crab Apple C2
- T15 Norway Maple

- T19 Ash ??
- G5 Leyland Cypress B2

The tree removals have to consider bat roosts and bird nesting. The felling and clearing of the trees will be undertaken between 1 October and 1 March inclusively. On site all trees felled to be stump ground out.

TREES TO BE RETAINED

- TPO T2 T1 Lebanon Cedar A2
- TPO T1 T2 Norway Maple B2
- T3 Birch B2
- T4 Birch B3
- TPO T3 T16 Wild Cherry B2
- TPO T4 T17 Weeping Willow
- G1 Leyland Cypress B2

OFF SITE TREES

- T12 Birch B2
- T13 Birch C2
- T14 Sycamore B2
- G2 Willow and Ash B2
- G3 2No Ash ??
- G4 Willow and Lime B2

TREEWORKS

The only treeworks required are monitoring the off-site G3 group of Ash for ash dieback disease.

3.0 TREE PROTECTION PLAN

ACTION

This (AMS) Arboricultural Method Statement is set out for the implementation of any aspect of the development that has the potential to result in the loss or damage to a tree. This AMS sets out the work which will be carried out at the Site area as follows:

- Installation of the protective fence and keep it in place until all construction is complete.
- Tree removals and treeworks as listed above to be undertaken
- Protective Fence barriers erected in the correct location.

TREE PROTECTION

The installation of the protective fencing shall be located as shown on

Drawing No CA 2022-02 Rev D Lidl Hereford Overlay & Tree Protection Plan for protection against damage to trees to be in accordance with BS 5837: 2012 – Trees in relation to Construction is to be a Heras Fence installed to the Figure 2 default specification.

A tree protection barrier was to be erected prior to any site activity starting and the construction exclusion maintained until the end of the construction period when the landscape works are undertaken.

No development shall take place except in complete accordance with the approved scheme, and works required by that scheme are in place. All protective fencing, etc shall be retained intact for the full duration of the development hereby approved, and shall only be removed, or altered in that time with the prior written approval of the Local Planning Authority.

Principal Contractor to maintain fence intact until construction works are complete and hand works may only commence within the protected and exclusion zone

TPO3 T16 WILD CHERRY

Refer to Drawing No CA HFD-2022-05 Lidl Hereford Willow and Cherry Close Up

The pond wall abuts into the potential RPA. The pond has vertical sides the depth of the pond **is** deep well over 1.00m in depth and there is a 0.80m height brick wall above the grass level. The water level is 55.94 and adjacent cherry tree ground level is 56.27m. It is likely that the cherry tree roots do not extend below the pond. The RPA in the soft landscape is provisional and its exact spread should be checked on site. The majority of the RPA has no restricted growth

TPO4 T17 WEEPING WILLOW

The pond wall abuts into the potential RPA. The pond has vertical sides the depth of the pond is well over 1.00m in depth and there is a 0.60m height brick wall above the grass level. The water level is 55.94 and adjacent willow ground level is 56.48m. It is likely that the willow tree roots do not extend below the pond. To the north of the pond are brick planters curved around a grass area and the willow roots are likely to extend into this area. To the west the willow RPA abuts the probable new road edge. To the south the willow extends south within a grass area.

The willow tree trunk is close to the pond wall edge and a large proportion of the potential root spread lost due the pond wall.

POND WALL

Refer to Drawing No CA HFD-2022-04 Rev A Lidl Hereford Landscape Sections

The pond wall will be demolished and the old pond area to be infilled. The old pond area will either be under proposed carparking or soft landscape areas.

- For the Cherry tree there will be a small amount of additional soft landscape area possible for root expansion beyond the old pond wall line.
- For the Willow tree there will be a large amount of additional soft landscape area possible for root expansion beyond the old pond wall line to the full extent of the Potential RPA line.

The infill up to 900mm below finished levels will be to the Engineer's detail after that it is proposed to have 600mm of subsoil with a 300mm topsoil cover to give a growing medium for tree roots.

4.0 PROPOSALS

The proposed redevelopment comprises the construction of a new Lidl store with a customer carpark.


There will be additional tree planting in the north western area of the site and along the northern boundary. The existing shrub bed on the east boundary will be retained and gaps infilled with tree planting between the existing planting bed and the rear of the store.

The site frontage landscape will be designed to make a positive impact on the streetscape and this will include tree planting. The importance of Lebanon Cedar is noted and this tree is retained with no impact on the tree or its roots by the proposed development. The adjacent beech hedge is to be retained and is an important frontage feature.

There new tree planting will be compensatory planting to mitigate the loss of the 10 Trees and a Leyland Cypress Group

ree Surv	vey -	Lidl, 10 Belmont	Road	ı, He	retord	- 16 12	∠∪∠1	rev 20 August 2022 - TPO trees added				
		DAVID RICE FORES	TDV					rev 14 Sept 2022				
		Forestry Consultancy										
		Cefnllwydcoed Salen	n Road		nybanc	Llandeile	o Carmarthei	nshire SA19 7LR				
		Telephone/Fax 01558						Irice2@talktalk.net				
		Collated and indicated	d on C	AD b	ase by	Corscado	den Associate	9 \$ 				
		KEY										
		<u></u>										
		AgeY=Young, SM=		matuı	re, MA=	Middle a	ged, M=Matu	re, OM= Overmature				
		Ht = Height in me		L .		ļ						
		<u>Diam</u> = Breast height Spd = Crown spread				neters						
		Clear = Height of cro					TPO TREES	Hereford 2022 (No 666) T1, T2, T3, T4				
		<u>Life</u> = Life expectancy						BE REMOVED TO FACILITATE DEVELOPMENT				
						<u> </u>						
		GRADE) years life es					
			C= T	rees (of low a	rate quar ralitv >10	ity >20 years) years life ex	life expectancy				
							years life ex					
					•			,				
						ıltural qu						
			2= M	ainly	landsca	pe qualit	ies including cor	pervation				
						nove/Fell		ioi vanoli				
		Root protection area						otection area as per BS5837:2012				
No		Species	Age	_	Stem		Spread m	Comments and Recommendations	Est	Gra	de	RPA
				m	diam	clear Ht/m	NESW		life years			radius m
TPO T2		Lebanon cedar	М	17	95 at	0	5 5 5 5	Ivy. Branched to ground level. Small deadwood	>40	Α	2	
	1				0.5 m			A well proportioned specimen in good health				
TPO T1	2	Norway maple	М	14				Overall crown reduction in the past and subsequent growth to result in well formed specimen	>40	В	2	
		Birch	M	18					>20	В	2	
		Birch Lime sps	M	16 16				Occluding branch scars.Some crown reduction in the	>20	В	2	
		Lime sps	M	15				past. Multibranched from 2m Occluding branch scars. Some crown reduction in the	>20	В	2	
	Ŭ	Line opo	'*'	'				past. Multibranched from 2m	20		-	7.2
	7	Lime sps	MA	15	24	2	3 3 3 3	Occluding branch scars. Some crown reduction in the	>20	В	2	2.9
				45	0.5		0 0 0 0	past	. 00		<u> </u>	1.0
		Lime sps Lime sps	MA MA	15 15				Occluding branch scars Occluding branch scars. Multitrunked from 1.5m	>20	B B	2	
		Crab apple	M		25,20	1.8		Topped at 3m and grown out. Branches rubbing roof of		В	2	
		hort var			13			adjacent building				
	11	Crab apple hort var	SM	4	14	1.8	2 2 2 2	Flat top	>10	С	2	1.7
	12	Birch	М	18	c 35	4	4 4 4 4	OFF SITE. Partial dead top. Hollow branch scar on	>10	С	2	4.2
								main trunk				
		Birch	MA		c 20	3		OFF SITE	>20	В	2	
	14	Sycamore	М	14	c40		3 over	OFF SITE. Vigorous ivy. Multi branched from 2m	>20	В	2	4.8
	15	Norway maple ?	SM	7	20	1.5	site 2 2 2 2		>10	С	2	2.4
TPO T3	10	Wild cherry	M		22,21	1.5		Four branches from 1m. Topped at 1.5m and grown ou		В	2	
	16	·			20,22							
TPO T4	17	Weeping willow	М	14			6666	Two trunks from 3m. A good specimen	>20	В	2	8.4
	18	Lime species	М	12	43	2	5 5 5 5	Basal epicormic shoots. Fruiting bodies of	<10	U	U	
								Ganoderma applanatum/australe at base of trunk.		-		
								This is a trunk and root rotting fungus Fell to ground level				
	19	Ash	М	17	47	4	6666	Occluding branch scars.	?			5.6
								No signs of active ash die back disease ADB				
								Monitor for ash die back disease in autumn 2022				
G1		Leyland cypress	М	16	to 75	3 in site	4 all round	Multitrunked from ground level. Crowns extend over sit	>20	В	2	9
G2		Willow and ash	M	to	to c 25		2 over site	OFF SITE Collapsing willow cut back to site boundary	<10	С	2	
				15				One ash without signs of ash die back disease				
G3		2no Ash	М	to18	c 45	3	5 over site	OFF SITE Very vigorous ivy, No obvious ash die back	?			5.4
								disease infection.				
G4		Willow and lime	М	to18	c 30	2	6 over site	Monitor for ADB autumn 2022 OFF SITE Vigorous ivy. Lime is just rescuable	>20	В	2	3.6
G5		Leyland cypress	MA	6			3 all round	Multi trunked from ground level	>20	В	2	
		J 5) p. 300		L				J. Santa 15. 5.				
								Notes				
				_				No life expectancy for ash due to likely ADB infection				
				1	-			All tree wrok to be to BS3998:2010		1		
				<u> </u>				,				
			_	_	_		_		_		-	-





E,mail davidrice2@talktalk.net

CA HFD 2022-01 Rev A

7 March 2022 Revised Trees

CA HFD 2022-01 Rev B

17 July 2022 T15 Norway Maple Retained

CA HFD 2022-01 Rev C

10 August 2022 T15 Norway Maple Retained and G8 Leyland Cypress block removed Willow still under review

CA HFD 2022-01 Rev D 20 August 2022

TPO trees indicated

CA HFD 2022-01 Rev E

14 Sept 2022 Additional tree info by Cherry

David Rice Forestry Cefnllwydcoed Salem Road. Llandeilo Carmarthenshire SA19 7LR Tel 01558 824019 davidrice2@talktalk.net

Collated on to CAD base by Corscadden Associates 77 Fairleigh Road Cardiff. CF11 9JW Tel 02920 373053 email ca@corscaddenassociates.com

THREE COUNTIES HOTEL HEREFORD

Drawing Title


173


TREE SURVEY AND **EXISTING FEATURES**


Date Scale 29 Dec 2021 1:500 at A2

Drawing No

CA HFD 2022-01 Rev E







Trees are planted in existing soil in part of the western section of the site. Where possible tree pits will use existing soil and where this is not available imported topsoil and subsoil will be imported.

EXTRA HEAVY STANDARD

WILDFLOWER GRASS AREAS

WILDFLOWER GRASS AREAS are on the western and northern side of the site and the majority are in existing grass areas. There is a small area around the ditch in the eastern corner of the site,

WILDFLOWER GRASS AREAS where it replaces hardstanding. 150mm -300mm Existingor imported Subsoil depth selected subsoil for minimal stone content over subgrade or made ground. To be seeded with Conservation Grass Mix and overseeded with wildflower mix as specified.


Existing Ground

300mm depth
Selected Subsoil
Minimal stone content

Existing Ground
or made ground
broken up to 300mm


WILDFLOWER GRASS AREAS
Maintain existing grass as specified and over seed with
wildflower mix as specified

Existing Topsoil




Part of the hedgerow will be in existing ground with the Root Protection Area of the G1 Leyland Cypress. The hedge plants will be slit planted in this area. The area of previous hard standing the area with cleared and a hedging trench provided. of 300mm subsoil, 300mm topsoil with a 1.00m width and soil cultivated and hedge plants planted..

BEECH HEDGEROW ON WESTERN SIDE




AMENITY GRASS AREAS

Existing amenity grass areas on the western section of the site around the T1 Lebanon Cedar and by the T3 and T4 Birches. New grass areas occur on the western side where existing carpark areas are removed and on the centre and east of the site around the building where grass areas are to be provided new areas to be cultivated and seeded with Conservation Grass



NATIVE STRIP

These are on the western and northern boundaries of the site.



CA HFD 2022-04 Rev A 14 Sept 2022 Section by willow

Notional location base of Pond

Willow potential RPA becomes available for the Cherry roots to spread into. The Willow roots can spread into the whole of the potential RPA area with the soft landscape areas now available. Pond Wall to be removed Extent of potential RPA Some state of potential RPA Bettent of potential RPA Bettent of potential RPA Bettent of potential RPA Bettent of potential RPA

WILLOW TREE SECTION

Infill material to Engineer's detail.

The Cherry tree has a small area of soft landscape in the old pond location and only part of the extent of the Cherry potential RPA becomes available for the Cherry roots to spread

Corscadden Associates 77 Fairleigh Road Cardiff. CF11 9JW Tel 02920 373053 email ca@corscaddenassociates.com

Project

THREE COUNTIES HOTEL HEREFORD

Drawing Title


LANDSCAPE

SECTIONS

Scale Date as given at A3 29 Dec 2021

173 CA HFD 2022-04 Rev A

Drawing No





Project
THREE COUNTIES HOTEL
HEREFORD

Drawing Title
CHERRY AND WILLOW
TREE CLOSE UP

CA HFD 2022-05 Rev A 22 Oct 2022 Revised Layout Scale Not to scale Date 14 Sept 2022

Drawing No

173

CA HFD 2022-05 Rev A