## c<sup>2</sup>designs chartered|structural|engineer







21035

Long Barn, Much Marcle, Herefordshire. For Emma & James Richardson.

## ADDENDUM TO STRUCTURAL CONDITION REPORT

## EAST BARN GABLE MASONRY

- 1.1. Further consideration has been given to the original report proposal, clause 8.1.8 of the Structural Condition report Issue 2, issued on the 19th April 2021 with regard to the east gable masonry. Carefully take down and rebuild of the east gable peak from approximately 1 metre above eaves level.
- 1.2. Whilst significant outward movement of the gable is evident, the inner and outer facing stonework of the gable do appear to be reasonably well bonded and integral.
- 1.3. It should be appreciate however, there is considerable face decay to the gable peak stonework to be assessed at close hand.
- 1.4. Consequently, and subject to final inspection once close access is permitted, the original proposal is being amended to the existing gable peak being retained insitu with as little rebuilding as is practically required and restrained back to the substantially reinforced roof structure.



Ian Ceney CEng. MIStructE