

APPENDIX A



fig.1

3.1.1 Some dampness was evident at ground floor slab level around the base of the load bearing timber post.



fig.2

3.2.1 Slight frost damage was noted to the external facing brickwork immediately above external ground floor level at the return to the north elevation



fig.3

3.3.1 There was considerable vegetation growth along this elevation precluding an inspection of the masonry at external ground floor level