




Scale bar 1:100



House Elevation Key:

- G** - Existing porch repaired in accordance with structural engineers guidance and tied in main house front wall.
- K** - Conservation, flush fitting aluminium conservation rooflights
- M** - Replace modern infil with sympathetic glazing to reveal diamond mullions.
- Q** - Stone chimney breast repointed and repaired where necessary
- S** - Existing window replaced in repaired gable wall
- T** - New window formed in gable wall
- U** - Roof repaired with reclaimed slate to match existing.
- V** - All stonework repaired using lime mortar to match existing. White limewash to all elevations
- V1** - As above (V) without limewash
- W** - Restore original timber windows to original operation
- X** - Gable end wall rebuilt in accordance with Structural Engineer's guidance. Stonework re-used and laid to match existing coursing, limewashed.
- Y** - Replace existing modern window with new frame to match original window configuration.
- Z** - Reinstate window opening
- AA** - Powder coated black aluminium rainwater goods.
- BB** - New oak plank door to match existing
- CC** - Existing door sympathetically repaired where necessary
- DD** - Pod materials to be timber clad to replicate simple wood
- EE** - Replace failed oak lintel

ARBOR

architects


Arbor Architects Ltd.
Shell Store, Skylon Park, Hereford, HR2 6JT
Registered No. 12037250

www.arborarchitects.co.uk

Notes

DESIGNERS HAZARD IDENTIFICATION:

Site Key:



Rev	Date	Description	DRW	CHK
Project Penymoor Farm				
Project No. 1037				
Date		Status		
18/Mar/24		PLANNING		
Scale		Drawn	Checked	
1:100 at A3		MH	EDS	
Drawing				
Proposed West & East Elevations - House				
Drawing No. PL601			Rev. A	