


APPENDIX B

SITE PHOTOGRAPHS



Photograph 1: View looking north-east through the site from the south-west corner.



Photograph 2: Concrete 'Wash-Down Area' in north-west corner of the site.



Photograph 3: Builder's Yard Area in the north of the site.



Photograph 4: Waste Oil Above Ground Storage Tank.



Photograph 5: Transformer to the east of the Electricity Substation.




Photograph 6: Waste drums of Hydraulic Oil & Lubricants left to the north of the Electricity Substation.




Photograph 7: Taped damaged areas in pACMs Insulation Board within the open fronted workshop building.



Photograph 8: Oil drum storage in open fronted workshop building.



Photograph 9: Car Battery Store in open fronted workshop building.



Photograph 10: Boarded Inspection Pit within Garage Building.