



| Key to Materials | |
|------------------|---|
| 1a | Stonework - existing to be repointed in lime mortar |
| 1b | Stonework - new with lime mortar pointing |
| 2a | Brickwork - existing |
| 2b | Brickwork - new |
| 3a | Framing - new - metal |
| 3b | Framing - new timber |
| 3c | Framing - original timber |
| 4 | Cladding - timber weather boarding |
| 5a | Door - new, timber, solid, boarded |
| 5b | Door - new, timber, solid with glazed panel |
| 5c | Door - glazed, metal frame |
| 6a | Glazed Unit - fixed - metal framed |
| 6b | Glazed Unit - opening - metal framed |
| 7 | Bat access point |
| 8a | Window - existing replacement - hardwood, painted |
| 8b | Window - modified opening - hardwood, painted |
| 8c | Window - new opening - hardwood, painted |
| 9a | Roofing - zinc |
| 9b | Roofing - clay tiled |
| 9c | Roofing - slate |
| 9d | Flat roof - single ply membrane |
| 10 | Flashing - metal |
| 10a | Rooflight - new, conservation type |
| 10b | Rooflight - new, flat |
| 11 | Metal rainwater goods |
| 12 | Painted Timber shutters |
| 13 | Traditional Lime Render with limewash finish |
| 14 | Flagstone steps |
| 15 | Planter |
| 16 | Insulated floor slab |
| 17 | Existing wall underpinned insulated and tanked |
| 18 | Access hatch to Bat Loft |
| 19. | Glazing behind timber boarding |

FARMHOUSE EAST ELEVATION

BARN EAST ELEVATION



P08