

Linhay Barn Key:


- A All stonework repaired using lime mortar to match existing.
- B New stonework to match existing.
- C New timber frame window with powder coated finish in existing opening.
- D New timber frame door with powder coated finish in existing opening.
- E Corrugated metal cladding to match existing.
- F Corrugated metal roofing colour TBC
- G Existing opening to be glazed and lintel repaired to match existing.
- H All rainwater goods in aluminium PPC, colour TBC
- I Louvred horizontal timber cladding to existing opening.
- J New Timber structural column.
 K Horizontal timber clad double doors
- L New metal fascia to match existing.
- M Existing opening, lintel retained.
- N Existing wall structure reclad with corrugated metal to match existing.
- O New corrugated metal clad doors to refuse store.
- P Existing roof structure reclad with corrugated metal to match existing.
- Q Minor repairs to existing roof where neccesary. R - ASHP
- S Timber column and joist structure retained and repaired where necessary.
- T Drainage gully in floor with appropriate



Notes

DESIGNERS HAZARD IDENTIFICATION:

Site Key:



Project

Penymoor Farm

Project No. 1037

Date Status 18/Mar/24 PLANNING Drawn Checked 1:100 at A3 MG MH

Drawing

Proposed First Floor Plan - Linhay

Rev.

Drawing No. PL321