

ĸ

10m

-PL622

A - All stonework repaired using lime mortar

- B New stonework to match existing. C - New timber frame window with powder D - New timber frame door with powder E - Corrugated metal cladding to match
- F Corrugated metal roofing colour TBC G - Existing opening to be glazed and lintel repaired to match existing.
- I Louvred horizontal timber cladding to
- L New metal fascia to match existing. M - Existing opening, lintel retained. N - Existing wall structure reclad with corrugated metal to match existing. O - New corrugated metal clad doors to
- P Existing roof structure reclad with corrugated metal to match existing. Q - Minor repairs to existing roof where
- S Timber column and joist structure retained and repaired where necessary. T - Drainage gully in floor with appropriate

ARBOR armiteuts		
Notes		
DESIGNERS HAZARD IDENTIFICATION:		
Site Key:		
Rev Date Description DRW CHK Project Penymoor Farm		
Project No. 1037		
Date 18/Mar/24	Status PLANNING	
Scale 1:100 at A3	Drawn MG	Checked MH
Drawing		
Proposed Ground Floor Plan - Linhay		
Drawing No. PL320 Rev.		Rev.