

## House Plan Key:

- **A** Remove inserted landing to reveal original room
- **B** Flagstone floor restored
- **B1** Flagstone floor restored lowered to match dining room
- C Restore original chimney breast
- **D** Timber frame partition and listed bench
- **E** Existing fire place, evidence of original fire place behind
- **F** Restore 19th century staircase
- **G** Existing porch repaired in accordance with structural engineers guidance and tied in main house front wall.
- H Underground drainage chanel installed to capture and channel water currenty flowing though house to be linked in with the repaired existing underground drainage system. under the floors running north to south.
- J Storage
- **K** Conservation, flush fitting aluminium conservation rooflights
- L Reinstate floor at first floor level
- **M** Replace modern infil with sypathethic glazing to reveal diamond mullions.
- **M1** Remove Modern infill and reinstate diamond mullions with glazed window internally
- N New door to bedroom
- O Timber floors connecting to gable wall repaired and supported on new gable end wall
- **P** New fire escape window
- **Q** Chimney breast repointed and repaired where necessary
- R Timber rafters restored where necessary
  S- Existing window replaced in repaired gable
- **S-** Existing window replaced in repaired gable wall
- T New window formed in gable wall
- **U-** Roof repaired with reclaimed slate to match existing.
- ${\bf BB}$  New oak plank door to match existing
- **CC** Existing door sypathetically repaired where necessary
- **DD** Pod materials to be timber clad to replicate simple wood
- EE ASHP
- **FF** Gable end wall rebuilt in accordance with Structural Engineer's guidance. Stonework re-used and laid to match existing coursing, limewashed.



armferf


Registered No. 12037250 www.arborarchitects.co.uk

Arbor Architects Ltd. Shell Store, Skylon Park, Hereford, HR2 6JT

Notes

DESIGNERS HAZARD IDENTIFICATION:

Site Key:



Grey indicates existing structure

Red indicates proposed structure

Dotted line indicates structure to be removed

\_\_\_\_\_ Dashed line indicates structure above

Refer to Arbor's Method Statement and the Structural Engineer's report for details of how works are to be carried out

lev	Date	Description	DRW	CHK

Project Penymoor Farm

Project No. 1037

Date		Status		
18/Mar/24		PLANNING		
Scale		Drawn	Checked	
1:100	at A3	МН	EDS	

Drawing

Proposed First Floor Plan - House

Drawing No. PL301 Rev. A

Scale bar 1:100

0 1 5 10