




- NEW SECTION OF BEAM
- NEW SECTION OF WALL PLATE
- NEW SECTION OF TRUSS RAFTER

1-2 COMMERCIAL ST
HEREFORD HR12 2AJ

SKETCH 01 1/120

STRUCTURAL TIMBER REPAIR



JAN 2020

1-2 COMMERCIAL ST
HEREFORD HRIZAJ

SKETCH 02 NTS

TIMBER REPAIR - TIE BEAM




JAN 2020



1-2 COMMERCIAL ST
HEREFORD HRIZAJ

SKETCH 03 NTS

TIMBER REPAIR - RAFTER
JAN 2020




1-2 COMMERCIAL ST
HEREFORD HR12AJ

SKETCH 04 NTS

TIMBER REPAIR - RAFTER/TIE BEAM

JAN 2020





1-2 COMMERCIAL ST
HEREFORD HR12AJ


SKETCH 05 NTS

TIMBER REPAIR - TIE BEAM/WALL PLATE

JAN 2020



TIE BEAM
235 MM
DEEP



WALL PLATE
125 MM
DEEP