



Home & Commercial

Tel: 01722 714455

Mob: 07904 093727

Email: ac@handc.co

Keeping buildings dry & free from timber decay • Insurance claim services

Appendix 1 – Photographs

1. Blocked gully to rear



2. Rainwater arrangement at front RH side of house allowing water to soak into wall



The Mill House,
Sutton Mandeville,
Salisbury, Wilts, SP3 5LZ

T: 01722 714455
M: 07904 093727
E: ac@pcse.co.uk

Vat reg. No 750 5205 60



3. Live Death Watch Beetle attack in post to front porch



4. Verge to roof slope at south east corner to be repaired



5. Death Watch Beetle (inactive) and historic wet rot beneath drawing room floor



6. Historic (inactive) infestation by common furniture beetle (CFB) beneath main stairs



7. Steel 'shoe' to support beam end in cellar 1



8. Historic wet rot decay to roof truss end in old tank cupboard (2nd floor)

