



no.12 north west elevation



no.14 south east elevation

new HW framed, ledged and braced vertical boarded door

35



isolated patch repointing, using a 1:2.5 NHL 2.5 naturally hydraulic lime mortar mix using purpose made / proper pointing tools that fit the joint width to ensure good compaction and remove all mortar droppings immediately


 \oslash

 \bigcirc


plaster repair to decorative cornice using a 1:2.5 NHL 2.5 naturally hydraulic lime mortar mix

masonry to be cleaned by specialist contractor to remove organic growth following removal of dead creepers/ root systems using DOFF/JOSS/TORC cleaning system

★ all roofs, ledges, gutters and valleys to be cleaned and all moss/ lichen growth to be removed and area treated using ROUNDUP PRO VANTAGE



no.15 north east elevation



no.13 south west elevation

