



Drawing No
749-03

NOTES

1. Perimeter masonry walls to kilns lined internally with insulation and plasterboard.
2. All internal partitions are new - form in studwork.
3. Trusses and purlins generally repaired and cleaned and left exposed.