From: Richard Lamb [mailto:richard@hookmason.co.uk]

Sent: 09 February 2018 14:23

To: Reed, Emily < Emily.Reed@herefordshire.gov.uk >

Cc: Patrick Vaughan >; Jane Coyle

Allan Park

Subject: Welsh Bicknor church. Ref. 172428 - Tower ground floor

Dear Emily

Regarding Condition 5. The brickwork of the old boiler and chimney have been removed.

This reveals areas of concealed stonework, with a small number of brick inserts and open sockets. These can be seen clearly on the attached record photographs.

There is some soot and minor loose material on the revealed surface and we would propose simply brushing down with a stiff bristle brush to remove anything that is loose.

There is no need for any repairs or alterations.

The revealed masonry will remain visible on completion of the works.

I would be pleased for you to pass this on to the conservation officer for confirmation of whether this information will allow discharge of the condition or whether anything else is required.

I look forward to hearing from you.

Regards

Richard Lamb
Director
for and on behalf of
Hook Mason Limited

Studio 2, Thorn Office Centre Rotherwas, Hereford, HR2 6JT



hookmasonarchitecture



Hereford: 01432 352299 ext: 216 Tewkesbury: 01452 899550 ext: 216 Haverfordwest: 01437 206215 ext: 216

e: richard@hookmason.co.uk
w: www.hookmason.co.uk





This message and its attachments contain confidential information. If you are not the intended recipient, you are strictly prohibited to disclose, copy, distribute or take any action in reliance on the contents of this information.

E-mail transmission cannot be guaranteed to be secure or error-free, as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message, which arise as a result of e-mail transmission. Hook Mason Ltd accepts no liability for any damage caused by any virus transmitted by this email.