

# Inspection Report

FreeFlow Drainage Ltd  
27 Hallam Drive  
Berwick Grange  
Shrewsbury  
Shropshire  
SY1 4EH

Section: <b>S48 - ROAD INTERCEPTOR VERGE</b>	Date: <b>2021-09-01</b>	Job Number: <b>TILLINGTON ROAD STORM OUTFALL</b>	Weather: <b>No rain or snow</b>	PLR: <b>X</b>
Operator: <b>SCOTT OVERTON</b>			Cleaned: <b>no</b>	

Place:	HEREFORD	Direction:	Downstream	Start ref:	S48
Road:	ROMAN ROAD	Catchment:	STORM	Start depth:	0m
Location:	Verge	Total Length:		End ref:	STORM INTERCEPTOR VERGE ROAD
		Pipe Length:	0m	End depth:	0m
Use:	Surface Water		Pipe Shape:	circular	
Year Laid:	2000		Width / Height:	300mm / 300mm	
Purpose:	Pre-adoption survey prior to vesting as public sewer		Flow Control:		
Lining:			Pipe Material:	polyvinyl chloride	
Comments:					

0.00m (S48)

Meterage	CD	Code	Observation	Video	Pic.
0.00m		MH	Start node type, manhole reference number: S48 STORM WATER MANHOLE IN ROAD VERG	00:00:01	(1)
0.27m		WL	Water level 10% WATER LEVEL IN PIPE	00:00:09	(2)
28.73m		CN	Connection other than junction from 11 O'Clock diameter: 150 mm GULLY	00:03:22	(3)
40.87m		CN	Connection other than junction from 11 O'Clock diameter: 150 mm GULLY	00:04:19	(4)
54.82m		CN	Connection other than junction from 12 O'Clock diameter: 150 mm GULLY	00:05:22	(5)
69.71m		CN	Connection other than junction from 12 O'Clock diameter: 150 mm GULLY	00:06:47	(6)
79.77m		MHF	Finish node type, manhole reference number: STORM INTERCEPTOR VERGE ROAD	00:07:45	(7)
79.81m		REM	General remark INTERCEPTOR AT ROAD VERGE	00:07:56	(8)

79.81m (STORM INTERCEPTOR VERGE ROAD)


Section: <b>S48 - ROAD INTERCEPTOR VERGE</b>	Date: <b>2021-09-01</b>	Job Number: <b>TILLINGTON ROAD STORM OUTFALL</b>	Weather: <b>No rain or snow</b>	PLR: <b>X</b>
Operator: <b>SCOTT OVERTON</b>			Cleaned: <b>no</b>	




(1)




(2)



(3)




(4)



(5)



(6)

 <b>FREEFLOW</b> DRAINAGE LTD <small>SPECIALISTS IN WASTE DISPOSAL &amp; DRAINAGE SERVICES</small>		<h1>Inspection Report</h1>		FreeFlow Drainage Ltd 27 Hallam Drive Berwick Grange Shrewsbury Shropshire SY1 4EH	
Section: <b>S48 - ROAD INTERCEPTOR VERGE</b>	Date: <b>2021-09-01</b>	Job Number: <b>TILLINGTON ROAD STORM OUTFALL</b>	Weather: <b>No rain or snow</b>	PLR: <b>X</b>	
Operator: <b>SCOTT OVERTON</b>			Cleaned: <b>no</b>		



Section: <b>S48 - ROAD INTERCEPTOR VERGE</b>	Date: <b>2021-09-01</b>	Job Number: <b>TILLINGTON ROAD STORM OUTFALL</b>	Weather: <b>No rain or snow</b>	PLR: <b>X</b>
Operator: <b>SCOTT OVERTON</b>			Cleaned: <b>no</b>	



(7)



(8)