

Images of England

[Back To Results](#) [Non Print Page](#)



© Mr John Drummond

IoE Number:	152452
Location:	PORTCULLIS LODGE AND RETAINING WALLS TO FORECOURT OF EASTNOR CASTLE,
	EASTNOR, HEREFORDSHIRE, HEREFORDSHIRE
Photographer:	Mr John Drummond
Date Photographed:	09 October 2002
Date listed:	10 January 1986
Date of last amendment:	10 January 1986
Grade	II

The Images of England website consists of images of listed buildings based on the statutory list as it was in 2001 and does not incorporate subsequent amendments to the list. For the statutory list and information on the current listed status of individual buildings please go to [The National Heritage List for England](#).

EASTNOR CP

EASTNOR

SO 73 NW
4/30

Portcullis Lodge and
Retaining Walls to

EASTNOR CP EASTNOR SO 73 NW 4/30 Portcullis Lodge and Retaining Walls to Forecourt of Eastnor Castle - GV II Lodge and retaining walls to forecourt. 1815-16 by Robert Smirke. Lodge of coursed squared rubble and freestone dressings; roof concealed behind embattled parapet. Single storey on battered basement. Central pointed archway. 2 stage round corner towers, on battered plinths. On the entrance front tower, narrow slit windows face inwards and round-head windows in deep freestone embrasures face outwards. Chamfered string course and panel of arms in the centre. 2 plank doors in pointed free- stone surrounds on inner side of archway. Flanking the

lodge are tall retaining walls which return towards the castle and enclose the forecourt: coursed rubble with freestone coping and embattled parapet; approximately 6 - 8 m high on the outside and buttressed at north corner.

Please note that the inclusion of a listed building on this website does not mean it is open to the public.