

WALL FRAME

WEST ELEVATION

SURVIVING
ORIGINAL TIMBER
AND STONE IN
AS SEEN
CONDITION

TIII

TII

TI

ORIGINAL CASEMENT WINDOWS WITH LATER GLASS AND GLAZING BARS

BATHROOM

HEREFORDSHIRE COUNCIL
PLANNING SERVICES
DEVELOPMENT CONTROL
To
Ack'd
15 APR 2015
File
OLD PANTRY WALL
↓

BLOCKED UP ORIGINAL FRONT DOOR
CEMENT AND BRICK

SCALE 1 : 25