

Field Reference 1097

CONDITION 6, 7, 8, 9, 10

LB

Graveyard

Chapel

CHAPEL PARKING

8m

10m

10m

GATE

3.7m

4.7m

8m

4.7m

HEREFORDSHIRE COUNCIL
PLANNING SERVICES
DEVELOPMENT CONTROL

20 JUL 2018

To.....
Ack'd..... File.....