

Images of England

NW / 092097 / FH
NW / 092093 / L

[Back To Results](#) [Non Print Page](#)



© Mr John Burrows DPAGB

IoE Number: 150391
Location: THE MALTHOUSE,
ALMELEY, HEREFORDSHIRE, HEREFORDSHIRE
Photographer: Mr John Burrows DPAGB
Date Photographed: 19 July 2007
Date listed: 16 July 1987
Date of last amendment: 16 July 1987
Grade: II

ALMELEY CP

ALMELEY WOOTTON

SO 35 SW
1/22

The Malthouse

GV

ALMELEY CP ALMELEY WOOTTON SO 35 SW 1/22 The Malthouse GV II House. Probably C18 with C19 and later alterations. Sandstone rubble and brick with timber-frame. Tiled roof with sandstone rubble and brick stacks. Rectangular plan of seven or eight structural bays aligned roughly east/west. Two storeys and attic. South elevation has two raking-top dormers, each with a 2-light late C19 casement, to left-hand side over C19 brick extension. Ground floor of brick extension has two early C19 wooden casements each of three lights, between which is a glazed early C19 porch. Rubble part, probably C18 is to centre and right. This has two first floor 2-light mid-C19 casements and a blocked opening to the right. Ground floor has three similar irregularly placed casements to ground floor. Entry to extreme right side, which is curved slightly back from the rest of frontage, with mid-C20 ledged door. West gable has rough-cast finish. North elevation has two sandstone rubble and brick stacks and cat-slide lean-to. Interior has a variety of trusses in C18 part. Two have curved raking struts, and others interrupted tie-beams. C19 part has collar trusses. Some timber-framed walling. Ground floor rooms have ceiling beams with straight-cut chamfer stops. Included for group value.

