3/63

Barn and attached granary about 20 yards north-east of Penny Pit

GV

II

Barn and granary. Barn is probably C17 with substantial C18 extensions and C19 alterations. Sandstone rubble plinth, timber-frame with some brick and woven infill but mainly weatherboarded, pantiled roof; L-plan with one older three-bay arm extending northwards and the other, probably of four bays, extending westwards towards the granary. South elevation has stable door to left of centre and two-leaved doors to right of centre; west elevation of north arm has one panel of riven oak infill to left of full-height ledged doors to threshing floor in the southernmost bay. Interior has massive tie-beams to north/south range with a double tie-beam at the southern end to provide a bearing for the roofing of the later east/ west range. Two close-set threshing floors set at right angles appear thus to have been created. Granary: probably early C19, is sandstone rubble with pantiled roof, three bays, two levels; south elevation has brick segmental heads to ground floor openings, one to left and to doorway to right with two square-headed loft openings; north elevation has stone tallet stairs leading to upper level entry on left hand side. Interior has pegged king-post trusses. Included for group value.

which have two recessed panels to each face and bud finials; outer ends of railings run into square section sandstone piers with ball finials.

SO 52 NW

LLANWARNE CP

3/40

Penny Pit (that part in Llanwarne CP)

G۷

ΙI

See under Penny Pit, Llandinabo CP.

SO 52 NW

LLANDINABO CE

3/40

Penny Pit (that part in Llandinabo CP)

G۷

II

Includes Penny Pit, Llanwarne CP.
Farmhouse. Probably C17 with early C19 alterations. Sandstone rubble finished partly in render, Welsh slate roof, large rubble side stack to west and brick stack to east side. Rectangular plan aligned roughly north/south. Cellar with two storeys. East entrance elevation has one window, a 2-light early C19 window to first floor and beneath it a restored 3-light chamfered mullioned window, probably C17; to the right is a glazed mid-C20 entrance porch beyond which projects, at right angles to the front, a large three-storey early C19 hipped roofed wing with three bays of segmental-headed windows. West elevation has segmentally-headed early C19 casements mainly with three lights. Interior of eastern three-storey projecting wing contains large plaster cowl rising from ground floor brick furnace to first floor level. Farm buildings associated with Penny Pit are listed under Llanwarne CP.